

Technical Notification

Document number: 95-130549

Dec – 2009

New software ver. 3.03 for EXPLORER® 700

Subject:

Please be informed that a new software version 3.03 for the EXPLORER® 700 has been released.

Priority:

- **MEDIUM:** It is recommended to apply this change / initiative to all units in stock. For units sold it is recommended to apply this change / initiative next time the system(s) is inspected.

Changes from ver. 3.02 to 3.03:

This is a bug fix release only

- Resolved packet loss on Streaming connections which could be seen as "noise" on video Streaming applications.


Action:

Download file 'EXPLORER_700_V3.03.zip' located at Thrane & Thrane extranet <http://extranet.thrane.com/Support.aspx> or at the Thrane & Thrane A/S eSupport <http://extranet.thrane.com/Support/Technical%20Support.aspx>
Save / extract to your hard disk.


The following will describe the procedure for installing Ver. 3.03 on EXPLORER® 700.

1. Make sure the EXPLORER terminal is switched on and connect the Ethernet cable to your PC.
2. Open your web-browser and open the Web Interface of the EXPLORER at address <http://192.168.0.1/>

3. Select 'Settings' and 'Upload'




4. Select 'Browse', locate the file 'E700_V303.dl' and chose 'Open'.




5. Choose 'Upload' and verify that the upload is in progress like below (status bar enabled in browser)

Continued...



6. Select again the address <http://192.168.0.1/> and verify the software version at 'Dashboard'.



End of updating procedure.

Thrane & Thrane
Global Technical Assistance Centre

Thrane & Thrane A/S · Lundtoftegaardsvej 93 D · DK-2800 Kgs. Lyngby · Denmark
T +45 39 55 88 00 · F +45 39 55 88 88 · info@thrane.com · www.thrane.com
Bank: Danske Bank · Comp.reg.: 65 72 46 18 · VAT: DK-20 64 64 46